STATION RECORD OF TRAIN MOVEMENTS

CT 355-A R2 10-76 PRINTED IN USA MU

CONSOLIDATED RAIL CORPORATION

REGION: Central | STATION: Rockville | DATE: April 16 1983

Operator	On Duty	Off Duty	Leverman	On Duty	Off Duty	Weather	Temp.	Time
W P McLean	12:1A M	7A M		M	M			
D L Kirby	7:00A M	3:00P M		M	M			
	M	M		M	M			
	M	M		M	M			

INSTRUCTIONS
1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
2. Each operator and leverman shall enter time on and off duty in the space provided.

TRANSFER RECORD

	AT 7A M	AT 3:00 P M	AT ____ M
TRAIN ORDERS TO BE DELIVERED	#102 #105 #106	No-102-105-106	
MESSAGES TO BE DELIVERED	5 to opr #5 #19 Sw RR	5-To oprs. Nos-5 & 19 Rusty Rail	
OVERDUE TRAINS	None #5 Sw Spiked	None No 5 spiked Normal	
TRAIN ORDER SIGNAL DISPLAYED	Yes-East #6 Sig at Stop	Yes East No 6 SIG. at Stop	
TRAIN ORDERS IN EFFECT	#102 #105 #106	No 102-105-106	
READ, UNDERSTOOD AND SIGNED	D L Kirby	R W Mowl	

yellow — West WARD — yellow — East WARD

TRAIN	ENG.	Time Block Given	Geeck Time Departed	Trk.	Time Block Received	Rockville Time Arrived	Trk.	Time Departed	Trk.	Time Block Cleared	REMARKS
BDA	Branch	#6 Signal				2	1141	2	555	BDR	
NoW	222	—	1238 PM		NoW To NoW		MTY		Hoppers		

TRAIN	ENG.	Time Block Given	Mingo Time Departed	Trk.	Time Block Received	Rockville Time Arrived	Trk.	Time Departed	Trk.	Time Block Cleared	REMARKS
UCI-3 D	105		PH			1233	2	1248	2	2A	Branch
Help	7799		Yd	W		1235	2	1248	2	2A	"
Con-Lite	7739	Yd	728	W			1	731	1		Rochester
NoW	1472	—	743AM		NoW To NW		IRON ORE				
NoW	222	—	1213PM		NoW To NoW		MICS FRT.				
Con-Lite	7739	3373	20	18	1653	7584					E D.W. Shanks → 6AM FIRE H. H-Hancock
UCI-3 D	107	103	101	105	J.E. Shertzer						Ind. Inside 11P.
	96X0	1249	D		Cab. 2176	3					
Help	7799	7869	P.		Stancheh	P. Schuberg					End Pilot 11P.