STATION RECORD OF TRAIN MOVEMENTS

CT 355-A R2 10-76 PRINTED IN USA MU

CONSOLIDATED RAIL CORPORATION

REGION: Central | STATION: Rahville | DATE: April 3 1983

Operator	On Duty	Off Duty	Leverman	On Duty	Off Duty	Weather	Temp	Time
W J McGraw	1201A M	4 A M		M	M			
G L Kirtley	7:00 A M	3:00 P M		M	M			
	M	M		M	M			
W J McGraw	M	M		M	M			

INSTRUCTIONS
1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
2. Each operator and leverman shall enter time on and off duty in the space provided.

TRANSFER RECORD

	AT 4A M	AT 3:00 P M	AT ___ M
TRAIN ORDERS TO BE DELIVERED	#103	No-103	
MESSAGES TO BE DELIVERED	5 to Dr #5 + 19 Sw RR	5-To oprs-Nos-5 & 19 SWTS-R.R.	
OVERDUE TRAINS	None #5 Spiked normal	None No 5-spiked Norm.	
TRAIN ORDER SIGNAL DISPLAYED	No #6 Sig at Stop	No No 6 SIG. AT STOP	
TRAIN ORDERS IN EFFECT	#103	No-103	
READ, UNDERSTOOD AND SIGNED	G L Kirtley - CT-405-R-11-Fulfilled	W J McGraw 1230A-	4-4-83

West WARD — Yellow Creek

TRAIN	ENG.	Time Block Given	Time Departed	Trk.	Time Block Received	Time Arrived	Trk.	Time Departed	Trk.	Time Block Cleared	REMARKS
Z-Yd	7552	Z-Yd	105	2			X	108	E	110	Yd-LITE
N&W	1341		1024AM		N&W	To N&W				17X	coke
N&W	1341		152PM		N&W	To N&W				LITE	

East WARD — PH Yd

TRAIN	ENG.	Time Block Given	Time Departed	Trk.	Time Block Received	Time Arrived	Trk.	Time Departed	Trk.	Time Block Cleared	REMARKS
Z-Yd	7252	Yd	1257	E			2	1K	2	103	Z-Yd-1X
W-MJ-12	3280	Yd	1247	W			1	1257	1		YC-
N&W	1373		1005AM		N&W	To N&W				17	Hoppers
N&W	1373		140PM		N&W	To N&W				12X	Scrap

(EB) Z-Yd 7252-1022 - (C) A.J. Wehr - (E) J.W. Hout - 7hrs - shv-1 car - CAB -

(WB) W1-MJ12 - 3280-8151 - (C) J.R. Sayre - (E) P. Roman - 1130AM - 3X-157-5010T

CAB 21201 DH-23541 - P.U. OHIO ED - AT Empire