

974#

CONSOLIDATED RAIL CORPORATION

REPORT DATE - 01/19/99 TIME - 07:08

PAGE - 1

REPORT NO. 010169

CT-78 UNUSUAL OCCURRENCE REPORT

PROGRAM - PL0204

\*\*

I D E N T I T Y

\*\*

3. TYPE - 03 (REAR END COLLISION)

4. TRACK CLASS - M (MAIN)

7. DATE : 01/17/99

8. TIME - 01:58 AM

6. DIVISION - 5 DEARBORN

REPORTING CDC - P4B

\*\*

L O C A T I O N

\*\*

9. LINE/BRANCH/YARD : CHGO. LINE

10. DODX EQUIPMENT N (NO)

11. PLACE : STRYKER

12. STATE : OH

13. RDBR : 0000

14. MILEPOST : 3372

15. TRACK NO : 0001

16. TRACK NAME : CHGO. LINE

17. HAZARDOUS MATERIAL INVOLVED : N

AUTHORIZED SPEED : 050 M P H

19. DESCRIPTION OF OBSTRUCTION(S) :

\*\*

T R A I N I N F O R M A T I O N

\*\*

20. TRAIN SYM : TV-7

21. LEAD ENGINE NO. : 4129

22. ADDL. UNITS : 1

23. DIRECTION : W

24. SPEED : 008 M P H

25. LOADS : 048

26. EMPTIES : 000

27. TONS : 03906

28. ENGINEMAN NAME : J SHARROCK

29. CONDUCTOR NAME : RA RUETZ

30. A C T I V I T I E S :

TV-7 ON APPROACH SIGNAL SLOWING PREPARED TO STOP. MAIL9  
BEHIND ON ONE TRACK WESTBOUND STRUCK REAR OF TRAIN  
DEFLECTING INTO MGL-16 EASTBOUND ON TRACK TWO.

31. ENGINES DERAILED : 3

32. NUMBER OF CARS DERAILED : 032

33. LOCATION OF DERAILED ENGINE(S)/CAR(S) WITHIN TRAIN :

\*\* R E L I E F F O R C E I N F O R M A T I O N \*\*

34. RELIEF FORCE NAME : CORMAN

35. RELIEF FORCE KIND : 2 (RAIL-HI CRANE)

36. CALLED : 01:30 AM

37. ARRIVED : 06:55 AM

38. COMPLETED : 00:00 AM

39. ADDITIONAL INFORMATION :

HULCHERS ALSO ASSISTED.

MAIL-9 CR6096 WITH 3 ADD'L 51/0 4966 TONS. CREW:

ENGR. RH BELL; COND. RE CORELL. 3 LOCOS AND 10 CARS

OF MAIL-9 DERAILED. MGL16 CR1697 & 3 ADD'L 0/62 1860TN

ENGR. LF LIPPERT; COND. JM GORDJEWSKI. 19 DERAILED

974#

CONSOLIDATED RAIL CORPORATION

REPORT DATE - 01/19/99 TIME - 07:08

PAGE - 2

REPORT NO. 010169 CT-78 UNUSUAL OCCURRENCE REPORT PROGRAM - PL0204

\*\* INJURY INFORMATION \*\*

- 40. PERSONAL INJURY INVOLVED : 1 (FATAL)
- 41. CLASS OF PERSON INVOLVED : 1 (EMPLOYEE ON DUTY)
- 42. DESCRIPTIONS/NAMES/DISPOSITIONS :  
ENGR: R.H. BELL; COND: R.E. CORELL CREW OF  
MAIL-9 BOTH KILLED.

\*\* CAUSE INFORMATION \*\*

- 43. CAUSE CODE : 799
- 44. CAUSE DESCRIPTION :  
UNDER INVESTIGATION

- 45. EQUIPMENT INVOLVED :
- 46. SECOND EQUIPMENT :

\*\* COST INFORMATION \*\*

- |                        |        |                        |        |
|------------------------|--------|------------------------|--------|
| 48. TRACK DAMAGE :     | 000000 | 49. SIGNAL DAMAGE :    | 000000 |
| 50. OTHER RR PROPERTY: | 000000 | 51. EQUIPMENT DAMAGE : | 000000 |
| 52. LADING LOSS :      | 000000 | 53. OTHER PROPERTY :   | 000000 |
| 54. WRECKING COST :    | 000000 | 55. OTHER COST :       | 000000 |

REMARKS :  
TOTAL DERAILED 3 ENG. AND 32 CARS IS TOTAL OF THE 3  
TRAINS INVOLVED.

REPORTS TRANSMITTED TO CDCS : CBK

THE ABOVE REPORT HAS BEEN TRANSMITTED

\*\*\* END OF REPORT \*\*\*