

974#

CONSOLIDATED RAIL CORPORATION

REPORT DATE - 05/17/94 TIME - 07:09

PAGE - 1

REPORT NO. 050143 CT-78 UNUSUAL OCCURRENCE REPORT PROGRAM - PL0204

*** C O N T E N T ***

3. TYPE - 01 (DERAILMENT) 4. TRACK CLASS - n (MAIN)

6. DIVISION - 6 (NORFOLK IS)

2. DATE : 05/17/94 8. TIME - 10:10 AM REPORTING CODE - P4B

*** C O N T E N T ***

9. LINE/BRANCH/YARD : COLUMBUS 10. BODX EQUIPMENT ID (NO)
11. PLANT - COLUMBUS 12. STATE - DE 13. RDRR : 0000
14. MILEPOST : 1397 15. TRACK NO : 0001 16. TRACK NAME : COLUMBUS
17. HAZARDOUS MATERIAL INVOLVED : N AUTHORIZED SPEED : 025 M P H
18. DESCRIPTION OF OBSTRUCTION(S) :

*** C O N T E N T ***

20. TRAIN SYM : PICO7 21. LEAD ENGINE NO. : 6255 22. ADDL. UNITS : 2
23. DIRECTION - N 24. SPEED : 024 M P H
25. LOADS : 074 26. EMPTIES : 084 27. TONS : 10615
28. ENGINEER NAME - JH CLARK 29. CONDUCTOR NAME : JM NIXON
30. A C T I V I T I E S :
NORMAL DECK MOVE DERAILED

31. ENGINES DERAILED : 0 32. NUMBER OF CARS DERAILED : 035
33. LOCATION OF DERAILED ENGINE(S)/CAR(S) WITHIN TRAIN :
2ND THRU 22ND & 50TH THRU 63RD

*** C O N T E N T ***

34. RELIEF FORCE NAME :
35. RELIEF FORCE KIND :
36. CALLED : 00:00 37. ARRIVED : 00:00 38. COMPLETED : 00:00
39. ADDITIONAL INFORMATION :

GTTX98533, GTTX985329, HTLX28357, CR495021, NS453840
LTTX985331, NH554125, NS453729, CR120758, CR598625,
HTLX41433, GATX89023, GATX36591, GATX89034, GATX14168,
LATX12950, LATX93182, KIBX9254, KIBX3533, LATX71777,
ACFX88787, NH178682, SOU88593, CR623883, SOU9593,

CONSOLIDATED RAD CORPORATION

REPORT DATE - 05/29/69 TIME - 07:09

PAGE - 1

REPORT NO. 050143 CT-78 UNUSUAL OCCURRENCE REPORT PROGRAM - PL0204

** C O N T E N T S **

- 40. PERSONAL INJURY INVOLVED : 0 (NONE)
- 41. CLASS OF PERSON INVOLVED :
- 42. DESCRIPTIONS/NAMES/DISPOSITIONS :

** F A C T S **

- 43. CAUSE CODE : 000
- 44. CAUSE DESCRIPTION :
UNDER INVESTIGATION

- 45. MEMBER INVOLVED : KTX98533
- 46. SECOND EQUIPMENT : KTX98533

** C O S T I N F O R M A T I O N **

48. TRUCK DAMAGE :	040000	49. SIGNAL DAMAGE :	003000
50. OTHER RR PROPERTY :	000000	51. EQUIPMENT DAMAGE :	500000
52. FACTORY LOSS :	000000	53. OTHER PROPERTY :	000000
54. WRECKING COST :	000000	55. OTHER COST :	070000

R E M A R K S :
ITLX30706, ITLX30658, ITLX30699, ITLX30772, CR608160,
PR608527, APTX200509, ACFX95901, CR889893, KATX129848

REPORTS TRANSMITTED TO CDCX : CBK

THE ABOVE REPORT HAS BEEN TRANSMITTED

** E N D O F R E P O R T **