

CONSOLIDATED RAIL CORPORATION

TRAIN ORDER No. 401

To CVE all Eastward train

March 25 1984

At Bayard

Do Not Exceed 25 MPH on No. 1
Track between MP 33.8 and MP 33.6
Temporary Speed Signs not in
Service

M.C.P.

annulled by order no 402
of March 26, 1984

Made Complete Time 1230 P. M. Operator Wagoner