

19

TRAIN ORDER No.

723

19

To

CTE Eastward Trains

Jan 15¹⁹ 77

At

Wanatah

Do not exceed 30 MPH on N^o1 track
between MP 339 and MP 338.6
account track condition. Speed limit
signs not in service

DKW

Made

com

Time

1240 a.m.

Operator

Tice T.K.