

REPORT DATE - 06/15/98 TIME - 09:44

PAGE - 1

REPORT NO. 060077

CT-78 UNUSUAL OCCURRENCE REPORT

PROGRAM - PL0204

**

I D E N T I T Y

**

3. TYPE - 01 (DERAILMENT)

4. TRACK CLASS - M (MAIN)

6. DIVISION - 6 INDIANAPOLIS

7. DATE : 06/04/98

8. TIME - 01:40 PM

REPORTING CDC - P4B

**

L O C A T I O N

**

9. LINE/BRANCH/YARD : SCOTTSLAWN 10. DODX EQUIPMENT N (NO)
 11. PLACE : HORTON 12. STATE : OH 13. RDBR : 0000
 14. MILEPOST : 0858 15. TRACK NO : 0000 16. TRACK NAME : SCOTTSLAWN
 17. HAZARDOUS MATERIAL INVOLVED : N AUTHORIZED SPEED : 050 M P H
 19. DESCRIPTION OF OBSTRUCTION(S) :

**

T R A I N I N F O R M A T I O N

**

20. TRAIN SYM : INCO-4 21. LEAD ENGINE NO. : 6619 22. ADDL. UNITS : 2
 23. DIRECTION : S 24. SPEED : 000 M P H
 25. LOADS : 042 26. EMPTIES : 026 27. TONS : 05697
 28. ENGINEMAN NAME : JF WATTS 29. CONDUCTOR NAME : CHEESEBREW
 30. A C T I V I T I E S :

NORMAL MOVE SOUTH WHEN WENT FROM MAIN TO INDUSTRIAL
 SIDING, CAUSING DERAILMENT

31. ENGINES DERAILED : 3 32. NUMBER OF CARS DERAILED : 013
 33. LOCATION OF DERAILED ENGINE(S)/CAR(S) WITHIN TRAIN :
 3 ENGINES & 1ST THRU 9TH CARS

** R E L I E F F O R C E I N F O R M A T I O N **

34. RELIEF FORCE NAME : CORMAN
 35. RELIEF FORCE KIND :
 36. CALLED : 02:20 PM 37. ARRIVED : 05:30 PM 38. COMPLETED : 00:00 AM
 39. ADDITIONAL INFORMATION :
 CR6619; CSXT6322; CR7707; SP16532; CR242747,
 CR242231; GTW105709; CPAA205986; CR239401; CR237109;
 CR240764; CR239801;
 THESE 4 CARS WERE IN THE GRAIN ELEVATOR:NAHX475431;
 OLDX7102; PLCX18618; CEFX15185

CONSOLIDATED RAIL CORPORATION

REPORT DATE - 06/15/98 TIME - 09:44

REPORT NO. 060077

CT-78 UNUSUAL OCCURRENCE REPORT

PROGRAM - PL0204

** INJURY INFORMATION **

- 40. PERSONAL INJURY INVOLVED : 0 (NONE)
- 41. CLASS OF PERSON INVOLVED :
- 42. DESCRIPTIONS/NAMES/DISPOSITIONS :

** CAUSE INFORMATION **

43. CAUSE CODE : 561

44. CAUSE DESCRIPTION :

SWITCH IMPROPERLY LINED.

THE CREW OF WSCO-12 WILL BE CHARGED WITH THE DERAILMENT

ENG: MJ NIGHTWINE-EMP# 628471; COND: JF JOHNSON

ENP# 696341.

45. EQUIPMENT INVOLVED : CR6619

46. SECOND EQUIPMENT : CSXT6232

** COST INFORMATION **

- 48. TRACK DAMAGE : 006000
- 50. OTHER RR PROPERTY: 000000
- 52. LADING LOSS : 000000
- 54. WRECKING COST, : 000000

- 49. SIGNAL DAMAGE : 000000
- 51. EQUIPMENT DAMAGE : 196367
- 53. OTHER PROPERTY : 000000
- 55. OTHER COST : 000000

REMARKS :

REPORTS TRANSMITTED TO CDCS : CBK CBK

THE ABOVE REPORT HAS BEEN TRANSMITTED

*** END OF REPORT ***